



# Condition Report

Date: 12/10/2023  
Property Condition: Repairable

Assignment Number  
484-310-0030-1

Loss Recap for Repairable  
Damage Appraisal...\$3,064.02  
Percent of ACV..... 25.32%  
Deductible.....\$1,000.00  
Total.....\$2,064.02  
Approximate ACV...\$12,100.00

Office:

Wichita Falls, TX (Corp) #484  
100 Energy Way Ste 1900  
FORT WORTH TX  
Phone: 888-970-3055  
Fax: 800-866-4732

Assignment Received: 10/31/2023

Date of Loss: 11/23/1923

Date of First Contact: 11/1/2023

Date of Inspection: 11/2/2023

Inspection Location:  
1215 E SCOTT WICHITA FALLS, TX 76301

Vehicle/Owner Information:

Insured: Clay County Chief Deputy Sharp  
Vehicle: 2015 Ford Taurus  
VIN #: 1FAHP2MK0FG182214

Repair Facility:

Ke vins Complete Paint & Body  
1215 E Scott Ave Wichita Falls, TX 76301  
Phone: (940) 322-5801  
Fax: (940) 767-5911

Tax# 75 2171725

## Loss Recap

Estimated Amount of Open Damages: 0.00  
Estimated Salvage Value: 0.00  
Repair Facility Estimate Amount: 0.00

Recommendation: Repairable  
Primary Damage: Right Front Corner  
Secondary Damage:  
Damage Appraisal: \$3,064.02

Claim #: APD20239387-1

Policy #:

Agreed Scope of Damage: Yes  
Days to Repair: 3  
Appearance Allowance: No

Betterment/Depreciation: No  
Applicable: False  
Reason:

Tow Charges: 0.00  
Storage Rate Per Day / Total: N/A

Direction to Pay: No  
Drivable: Yes

## Condition Summary

Interior: Good  
Paint: Good

Engine:  
Mileage: 67311

Special Equipment:  
POLICE PACKAGE

Approx Cost of Special  
Equipment: 0.00

### Tire Information:

Tread Depth:  
(in 32nd's)  
LF:7 RF: 7  
LR:7 RR: 7  
Spare:0

Size: 245/55/18  
Type: FIRESTONE

Remarks

Open Items

SUPPLEMENT COMPLETE

SUPPLEMENT COMPLETE.

**Alacrity Solutions Wichita Falls TX**  
PO Box 471909, FORT WORTH, TX 76147  
Office: (888) 970-3055  
Fax: (800) 866-4732  
wichitafalls@alacritysas.com

Estimate ID  
484-310-0030  
S1  
Quote ID  
131000120  
Claim Number  
APD20239387-1

For all supplements or inquiries, please refer to contact information above.

Insured  
Clay County Chief Deputy Sharp  
215 W Gilbert St  
Henrietta, TX 76365  
(940) 538-5611 (Work)  
trent.sharp@co.clay.tx.us

Appraiser  
Dustin Buckley  
Classification  
None

Supplemented By  
Dustin Buckley  
Classification  
None

Insurance Carrier  
TEXAS ASSOCIATION OF  
COUNTIES

**Additional Information**

CONTACT DATE  
Wed Nov 01 2023 11:08:00  
GMT-0500 (Central Daylight  
Time)

---

**TEXAS ASSOCIATION OF COUNTIES**

Loss Type Collision	Claim Number APD20239387-1	Adjuster Stephen Sanchez (512) 615-8996 (Work) stephens@county.org	Deductible 1000.00 - Not Waived
Loss Date 11/23/1923	Inspection Site Clay County Chief Deputy Sharp 215 W Gilbert St Henrietta, TX 76365 (940) 538-5611 (Work)	Inspection Date 11/2/2023	

**Additional Information**

UNDERWRITING COMPANY N/A	FULL CLAIM NUMBER APD20239387-1	INSURANCE CARRIER TEXAS ASSOCIATION OF COUNTIES	CARRIER STREET ADDRESS 1204 SAN ANTONIO
CARRIER CITY, STATE, ZIP AUSTIN, TX 78701			

## 2015 Ford Taurus Police 4 Door Sedan 3.7L 6 Cyl Gas Injected 6 Speed Auto Trans AWD

Exterior Color <b>G1 (Absolute Black)</b>	Interior Color <b>BLACK</b>	License <b>TX-1551748</b>	VIN <b>1FAHP2MK0FG182214</b>
Condition <b>Good</b>	Drivable <b>Yes</b>	Odometer <b>67311</b>	Production Date <b>07/2015</b>

Mitchell Service Code  
**911354**

Primary Point of Impact  
**Right Front Corner (1)**

Prior Damage Notes  
**NONE**

Options

Air Conditioning	All Wheel Drive	AM-FM Stereo	Anti-Lock Brake Sys. (ABS)	CD Player
Cloth Seat	Cruise Control	Driver Seat With Power Lumbar Support	Driver-Front Air Bag	Electric Defogger
Electronic Stability Control	First Row Bucket Seat	Left-Curtain Air Bag	MP3 Player	Passenger-Front Air Bag
Power Door Locks	Power Driver Seat	Power Remote Mirror	Power Steering	Power Windows
Power-Adjustable Pedals	Rear Bench Seat	Second Row Side Airbag With Head Protection	Side Airbags	Steering Wheel Mounted Audio Control
Tilt Steering Wheel	Tire Pressure Monitoring System	Traction Control/Electronic System	Trip Computer	

## Clay County Chief Deputy Sharp | 2015 Ford Taurus Police

Parts Profile  
**TEXAS PARTS**

Parts Profile Version  
**7.0**

Line #	Description	LABOR				PART				
		Operation	Type	Total Units	CEG	Type	Number	Qty	Total Price	Tax
<b>Front Bumper</b>										
1	AUTO Frt Bumper Cover Assy	Overhaul	Body	2.1#	2.1	Existing				
S1 2	101817 Frt Bumper Cover	Remove / Replace	Body	INC#	2.1	New	EG1Z 17D957 DPTM	1	\$543.33	Yes
S1 3	AUTO Frt Bumper Cover	Refinish Only	Refinish	3.4* C	3.2					
4	900501 Modified Refinish With Full Clear Coat									
<b>Front Lamps</b>										
S1 5	100552 L Front Combination Lamp	Remove / Install	Body	0.4*#	0.3	Existing				
S1 6	AUTO Frt Bumper Cover	Remove / Install	Body	INC	1.2					
S1 7	101944 R Frt Combination Lamp Assembly	Remove / Replace	Body	0.5*#	0.3	New	DG1Z 13008 AA	1	\$838.02	Yes
S1 8	AUTO Headlamps	Check / Adjust	Body	0.4	0.4					
S1 9	900500 REPAIR HEADLAMP	Additional Labor	Body*	1.0*	0.0	Existing				

Line #	Description	LABOR				PART					
		Operation	Type	Total Units	CEG	Type	Number	Qty	Total Price	Tax	
10	900501	New lamp on backorder. Time for temp repair until noew lamp comes in.									
S1 11	900500	Rewire Lamps for Custom Flashers	Additional Labor	Body*	1.2*	0.0	Existing				
<b>Trans Oil Cooler</b>											
12	101573	Trans Oil Cooler -M	Remove / Replace	Mechanical	0.8#	0.8	Aftermarket New	79271	1	\$113.00	Yes
<b>Front Fender</b>											
S1 13	100702	R Fender Liner	Remove / Replace	Body	0.4	0.4	New	BG1Z 16102 A	1	\$55.35	Yes
S1 14	100703	L Fender Liner	Remove / Replace	Body	0.4	0.4	New	BG1Z 16103 A	1	\$57.85	Yes
<b>Front Inner Structure</b>											
S1 15	100718	Lwr Frt Body Air Deflector	Remove / Replace	Body	0.3	0.3	New	DG1Z 8327 A	1	\$117.72	Yes
<b>Rocker / Pillars / Floor</b>											
16	101052	R Frt Rocker Moulding	Remove / Replace	Body	0.2	0.2	New	BG1Z 5410176 BA	1	\$126.75	Yes
<b>Additional Costs &amp; Materials</b>											
17	AUTO	Paint/Materials	Additional Cost							\$228.80*	Yes
18	AUTO	Hazardous Waste Disposal	Additional Cost							\$3.00*	Yes
19	936014	Flex Additive	Additional Cost							\$8.00*	Yes
<b>Additional Operations</b>											
20	933003	Tint Color	Additional Operation	Refinish	0.5*	0.0					\$0.00
21	933018	Mask For Overspray	Additional Operation	Body*	0.3*	0.0					\$5.00*
22	931127	Pre Repair Scan	Additional Operation	Mechanical	0.5*	0.0					\$0.00
23	931128	Post Repair Scan	Additional Operation	Mechanical	0.5*	0.0					\$0.00
24	AUTO	Clear Coat	Additional Operation	Refinish	1.3	0.0					\$0.00

\* Judgment Item

T Included in Two Tone Calculation

# Labor Note Applies

d Discontinued by Manufacturer

C Included in Clear Coat Calculation

A Included in Clear Coat and Two Tone Calculation

r CEG R&R Time Used for this Labor Operation

[ ] Verify the part number and price before ordering

## Parts Vendors

**PERFORMANCE RADIATOR**  
 2501 W GRAND AVE.  
 MARSHALL TX 75670  
 (903) 935-5015 (Work)  
 (877) 723-4286 (Work)

Line	Part #	Total Price
12	79271	\$113.00

**Disclaimer:** This estimate has been prepared based on the use of replacement parts supplied by a source other than the manufacturer of your motor vehicle. Warranties applicable to these replacement parts are provided by the manufacturer or distributor of these parts rather than the manufacturer of your vehicle.

**Estimate Totals**

Labor	Units	Rate	Sublet Add'l Amount	Totals
Body Labor	7.2	\$66.00	\$5.00	\$480.20
Refinish Labor	5.2	\$60.00		\$312.00
Mechanical Labor	1.8	\$100.00		\$180.00
<b>Total Labor</b>	<b>14.2</b>			<b>\$972.20</b>
			Taxable	\$972.20
			Tax 0.0000%	\$0.00
			Non-Taxable	\$0.00
			<b>Labor Total</b>	<b>\$972.20</b>
Parts	Amount			Totals
Taxable Parts	\$1,852.02			\$1,852.02
			Parts Adjustments	\$0.00
			Tax 0.0000%	\$0.00
			Non-Taxable	\$0.00
			<b>Parts Total</b>	<b>\$1,852.02</b>
Costs	Amount			Totals
Other Additional Costs	\$11.00			\$11.00
Paint Materials	\$228.80			\$228.80
			Taxable	\$239.80
			Tax 0.0000%	\$0.00
			Non-Taxable	\$0.00
Paint Materials Rate: \$44.00				
Rate Max: 99.9 units				
Additional Rate: \$0.00				
			<b>Costs Total</b>	<b>\$239.80</b>
Gross Totals	Amount			Totals
Gross Total	\$3,064.02			\$3,064.02
			Taxable	\$3,064.02
			Tax	\$0.00
			Non-Taxable	\$0.00
			<b>Gross Total</b>	<b>\$3,064.02</b>
Adjustments	Amount			Totals
Deductible	-\$1,000.00			-\$1,000.00
<b>Total Customer Responsibility</b>				<b>-\$1,000.00</b>
			<b>Net Estimate Total</b>	<b>\$2,064.02</b>
			Less Original Net Total	\$1,358.33
			Net Supplement Amount	\$705.69
			<b>S1: Dustin Buckley</b>	<b>\$705.69</b>

\*\*\*\*\*Notice\*\*\*\*\*

This appraisal is subject to the complete review and approval by the assigning insurance company to assure accuracy, cost effectiveness, and that accepted industry repair standards are met. The insurance company listed has the right to accept or reject any part or all of this appraisal or make any changes they feel necessary.

\*\*\*\*\*Notice\*\*\*\*\*

This is not an authorization for repair. All costs of repairs are the sole responsibility of the vehicle owner, who must authorize all repairs. Failure to deliver a copy of this appraisal to the repair shop by the vehicle owner may result in out of pocket expense to the

vehicle owner. Providing a copy of this appraisal is not an acceptance of coverage or liability and all issues of coverage or liability are to be determined by the insurance carrier.

\*\*\*\*\*Notice\*\*\*\*\*

Deductibles may or may not be addressed or included in this appraisal. If applicable, the repairer should collect the deductible from the vehicle owner prior to the release of the repaired vehicle.

\*\*\*\*\*Notice\*\*\*\*\*

It is the repairer's responsibility to send notification of the supplement via fax or email including a statement whether the repairs have been halted on the vehicle. Alacrity Solutions will respond to your request within 24 hours. Please allow 48 hours to complete supplement processing from the date of request to ensure timely release of the vehicle.

Disclaimer: Any person who knowingly presents a false or fraudulent claim for payment of a loss or benefit or knowingly presents false information in an application for insurance is guilty of a crime and may be subject to fines and confinement in prison.

**Estimate Event Log**

<b>Job Created</b>	10/31/2023 03:20 PM
<b>Supplement 1 Started</b>	11/2/2023 10:11 AM
<b>Supplement 1 Printed</b>	12/10/2023 10:16 AM
<b>Supplement 1 Committed</b>	12/10/2023 10:16 AM
<b>Estimate Version</b>	1

Date: 12/10/2023 10:16:57 AM  
 Estimate ID: 484-310-0030  
 Supplement: 1 - 12/10/2023 10:16:56 AM  
 Profile ID: South Central Profile

Supplement Delta Report  
 Comparison of Estimate 484-310-0030 Supplement 0 and Supplement 1

Damage Assessed By: Dustin Buckley  
 Supplemented By: Dustin Buckley

Insured: Clay County Chief Deputy Sharp  
 Vehicle: 2015 Ford Taurus Police  
 Date of Loss: 11/23/1923

Line Item	Labor Type	Operation	Line Item Description	Part Type/Num	Dollar Amount	Labor Units	CEG Unit
<b>Changed Entries</b>							
11	Body	REMOVE/REPLACE	R Frt Rocker Moulding	New BG1Z 5410176 BA	126.98	0.20	0.20T
16<	Body	REMOVE/REPLACE	R Frt Rocker Moulding	New BG1Z 5410176 BA	126.75<	0.20	0.20T
12		ADD'L COST	Paint/Materials		220.00*		T
17<		ADD'L COST	Paint/Materials		228.80* <		T

<b>Deleted Entries</b>							
2	Body	REMOVE/REPLACE	Frt Bumper Cover	Remanufactured FO1000672R	436.00	INC	2.10T
3	Refinish	REFINISH	Frt Bumper Cover			3.20	3.20
4	Body	REMOVE/REPLACE	R Frt Combination Lamp Assembly	Remanufactured FO2503336R	617.00	0.30	0.30T
5	Body	REMOVE/INSTALL	Frt Bumper Cover			INC	1.20
8	Body	REMOVE/REPLACE	R Fender Liner	Aftermarket New 12475-00496	35.00	0.40	0.40T
9	Body	REMOVE/REPLACE	L Fender Liner	Recycled ~301710253	35.00	0.40	0.40T
10		LINE MARKUP	Line Markup 25.0%		8.75		

**Added Entries**

New

2	Body	REMOVE/REPLACE	Frt Bumper Cover	EG1Z 17D957 DPTM	543.33	INC	2.10T
3	Refinish	REFINISH	Frt Bumper Cover			3.4*	3.20
4			Modified Refinish With Full Clear Coat				
5	Body	REMOVE/INSTALL	L Front Combination Lamp	Existing Existing	0.00	0.4*	0.30
6	Body	REMOVE/INSTALL	Frt Bumper Cover			INC	1.20
7	Body	REMOVE/REPLACE	R Frt Combination Lamp Assembly	New DG1Z 13008 AA	838.02	0.5*	0.30T
9	Body	ADD'L LABOR	REPAIR HEADLAMP	Existing Existing	0.00*	1.0*	0.00
10			New lamp on backorder. Time for temp repair until noew lamp comes in.				
11	Body	ADD'L LABOR	Rewire Lamps for Custom Flashers	Existing Existing	0.00*	1.2*	0.00
13	Body	REMOVE/REPLACE	R Fender Liner	New BG1Z 16102 A	55.35	0.40	0.40T
14	Body	REMOVE/REPLACE	L Fender Liner	New BG1Z 16103 A	57.85	0.40	0.40T
15	Body	REMOVE/REPLACE	Lwr Frt Body Air Deflector	New DG1Z 8327 A	117.72	0.30	0.30T

### Global Changes

No Deductible, Deductible Reduction Credit, Customer Responsibility, Labor Rate, or Part Adjustment changes were made.

		Amount
	Original Estimate	1,358.33
	Supplement 1	705.69
	Net Supplement Amount	705.69
<hr/>		
	Net Total	2,064.02
	Program Calc Version	Data Versions
	Supp 0	OCT_23_V
	Supp 1	DEC_23_V



**Software  
Version:** 23.4

**Copyright (C) 1994 - 2023 Mitchell International  
All Rights Reserved**



# Kevin's Complete Paint & Body

kevinspb21@gmail.com  
1215 E Scott Ave, Wichita Falls, TX 76301  
Phone: (940) 322-5801

Workfile ID: a434089a  
PartsShare: 7HFKJS  
Federal ID: 75-2171725

## Preliminary Supplement 1 with Summary

**Customer: sharp, clay co chief deputy**

**Job Number:**

Written By: Kaine Hibbs

Insured: sharp, clay co chief deputy      Policy #:      Claim #: APD20239387-1  
Type of Loss:      Date of Loss:      Days to Repair: 0  
Point of Impact: 12 Front

**Owner:** sharp, clay co chief deputy  
**Inspection Location:** Kevin's Complete Paint & Body  
1215 E Scott Ave  
Wichita Falls, TX 76301  
Repair Facility  
(940) 322-5801 Business  
**Insurance Company:**

## VEHICLE

2015 FORD Police Interceptor AWD (Fleet) 4D SED 6-3.7L Gasoline Sequential MPI

VIN: 1FAHP2MK0FG182214      Interior Color:      Mileage In:      Vehicle Out:  
License:      Exterior Color:      Mileage Out:  
State:      Production Date:      Condition:      Job #:

### TRANSMISSION

Automatic Transmission  
4 Wheel Drive

### POWER

Power Steering  
Power Brakes  
Power Windows  
Power Locks  
Power Mirrors  
Power Driver Seat  
Power Adjustable Pedals

### DECOR

Dual Mirrors

Tinted Glass

Overhead Console

### CONVENIENCE

Air Conditioning  
Intermittent Wipers  
Tilt Wheel  
Cruise Control  
Rear Defogger  
Message Center  
Steering Wheel Touch Controls  
Telescopic Wheel

### RADIO

AM Radio

FM Radio

Stereo

Search/Seek

CD Player

### SAFETY

Drivers Side Air Bag  
Passenger Air Bag  
Anti-Lock Brakes (4)  
4 Wheel Disc Brakes  
Front Side Impact Air Bags  
Head/Curtain Air Bags

### SEATS

Cloth Seats

Bucket Seats

Reclining/Lounge Seats

### WHEELS

Styled Steel Wheels

### PAINT

Clear Coat Paint

### OTHER

Traction Control  
Stability Control  
California Emissions

**Preliminary Supplement 1 with Summary**

**Customer: sharp, clay co chief deputy**

**Job Number:**

2015 FORD Police Interceptor AWD (Fleet) 4D SED 6-3.7L Gasoline Sequential MPI

Line	Oper	Description	Part Number	Qty	Extended Price \$	Labor	Paint
1		<b>FRONT BUMPER</b>					
2	S01	O/H front bumper				2.6	
3	S01	Repl Bumper cover	EG1Z17D957DPTM	1	539.98	Incl.	3.4
		Note: keystone bumper was not CAPA and poor fit					
4	S01	Add for Clear Coat					1.4
5		<b>FRONT LAMPS</b>					
6	S01	R&I LT R&I headlamp assy				0.3	
7	S01	Repl RT Headlamp assy to 02/03/2014	DG1Z13008AA	1	832.57	0.5	
		Note: police interceptor style lamp- unable to source a/m or reconditioned					
8		Aim headlamps				0.5	
9	*	S01	Rpr LT Headlamp assy to 02/03/2014			<u>1.0</u>	
		Note: lamp is broken. lamp was also on backorder. had to repair this lamp					
10	#	S01	Rpr rewire lamps- modified for custom flashers			1.0 M	
11		<b>RADIATOR SUPPORT</b>					
12	S01	Repl Lower deflector	DG1Z8327A	1	116.95	0.4	
13		<b>COOLING</b>					
14	**	Repl A/M Trans cooler	DG1Z7A095D	1	<u>113.00</u>	<u>0.8</u> M	
15		<b>FENDER</b>					
16	S01	Repl LT Fender liner	BG1Z16103A	1	57.85	0.4	
17	S01	Repl RT Fender liner	BG1Z16102A	1	55.31	0.4	
18		<b>PILLARS, ROCKER &amp; FLOOR</b>					
19	*	Repl RT Rocker molding front from 05/03/2011	BG1Z5410176BA	1	<u>126.98</u>	<u>0.2</u>	
20		<b>VEHICLE DIAGNOSTICS</b>					
21	*	Rpr Pre-repair scan				m <u>0.5</u> M	
22	*	Rpr Post-repair scan				m <u>0.5</u> M	
23		<b>MISCELLANEOUS OPERATIONS</b>					
24	#	Subl Hazardous waste		1	3.00		
25	#	Repl Flex additive		1	8.00 T		
26	#	Color tint / color match		1			0.5
27	#	Repl Cover Car		1	5.00 T	0.3	
28	#	Rpr deduct to match estimate				-0.5	
<b>SUBTOTALS</b>					<b>1,858.64</b>	<b>8.9</b>	<b>5.3</b>

**Preliminary Supplement 1 with Summary**

**Customer: sharp, clay co chief deputy**

**Job Number:**

2015 FORD Police Interceptor AWD (Fleet) 4D SED 6-3.7L Gasoline Sequential MPI

**ESTIMATE TOTALS**

<b>Category</b>	<b>Basis</b>	<b>Rate</b>	<b>Cost \$</b>
Parts			1,845.64
Body Labor	6.1 hrs @	\$ 66.00 /hr	402.60
Paint Labor	5.3 hrs @	\$ 60.00 /hr	318.00
Mechanical Labor	2.8 hrs @	\$ 100.00 /hr	280.00
Paint Supplies	5.3 hrs @	\$ 44.00 /hr	233.20
Miscellaneous			13.00
Subtotal			3,092.44
<b>Grand Total</b>			<b>3,092.44</b>

**Preliminary Supplement 1 with Summary**

**Customer: sharp, clay co chief deputy**

**Job Number:**

2015 FORD Police Interceptor AWD (Fleet) 4D SED 6-3.7L Gasoline Sequential MPI

**SUPPLEMENT SUMMARY**

Line	Oper	Description	Part Number	Qty	Extended Price \$	Labor	Paint
<b>Deleted Items</b>							
1		<b>FRONT BUMPER</b>					
2		O/H front bumper				-2.6	
3	** <>	Repl A/M Bumper cover	EG1Z17D957DPTM	1	<u>-436.00</u>	Incl.	<u>-3.2</u>
4		Add for Clear Coat					-1.3
6	**	Repl RECOND RT Headlamp housing	DG1Z13008N	1	<u>-617.00</u>	<u>-0.2</u>	
10		<b>FENDER</b>					
11	*	Repl LKQ LT Fender liner	BG1Z16103A	1	<u>-35.00</u>	<u>-0.4</u>	
12	*	Repl LKQ RT Fender liner +25%	BG1Z16102A	1	<u>-43.75</u>	<u>-0.4</u>	
<b>Added Items</b>							
1		<b>FRONT BUMPER</b>					
2	S01	O/H front bumper				2.6	
3	S01	Repl Bumper cover	EG1Z17D957DPTM	1	539.98	Incl.	3.4
		NOTE: keystone bumper was not CAPA and poor fit					
4	S01	Add for Clear Coat					1.4
6	S01	R&I LT R&I headlamp assy				0.3	
7	S01	Repl RT Headlamp assy to 02/03/2014	DG1Z13008AA	1	832.57	0.5	
		NOTE: police interceptor style lamp- unable to source a/m or reconditioned					
9	*	S01	Rpr LT Headlamp assy to 02/03/2014			<u>1.0</u>	
		NOTE: lamp is broken. lamp was also on backorder. had to repair this lamp					
10	#	S01	Rpr rewire lamps- modified for custom flashers			1.0	M
11		<b>RADIATOR SUPPORT</b>					
12	S01	Repl Lower deflector	DG1Z8327A	1	116.95	0.4	
15		<b>FENDER</b>					
16	S01	Repl LT Fender liner	BG1Z16103A	1	57.85	0.4	
17	S01	Repl RT Fender liner	BG1Z16102A	1	55.31	0.4	
<b>SUBTOTALS</b>					<b>470.91</b>	<b>3.0</b>	<b>0.3</b>

**Preliminary Supplement 1 with Summary**

---

**Customer: sharp, clay co chief deputy**

**Job Number:**

2015 FORD Police Interceptor AWD (Fleet) 4D SED 6-3.7L Gasoline Sequential MPI

**TOTALS SUMMARY**

<b>Category</b>	<b>Basis</b>	<b>Rate</b>	<b>Cost \$</b>
Parts			470.91
Body Labor	2.0 hrs @	\$ 66.00 /hr	132.00
Paint Labor	0.3 hrs @	\$ 60.00 /hr	18.00
Mechanical Labor	1.0 hrs @	\$ 100.00 /hr	100.00
Paint Supplies	0.3 hrs @	\$ 44.00 /hr	13.20
Subtotal			734.11
<b>Total Supplement Amount</b>			<b>734.11</b>
<b>NET COST OF SUPPLEMENT</b>			<b>734.11</b>

**CUMULATIVE EFFECTS OF SUPPLEMENT(S)**

Estimate	2,358.33	Kaine Hibbs
Supplement S01	734.11	Kaine Hibbs
<b>Job Total:</b>	<b>\$ 3,092.44</b>	

---

## Preliminary Supplement 1 with Summary

**Customer: sharp, clay co chief deputy**

**Job Number:**

2015 FORD Police Interceptor AWD (Fleet) 4D SED 6-3.7L Gasoline Sequential MPI

Estimate based on MOTOR CRASH ESTIMATING GUIDE and potentially other third party sources of data. Unless otherwise noted, (a) all items are derived from the Guide DR2JN10, CCC Data Date 11/15/2023, and potentially other third party sources of data; and (b) the parts presented are OEM-parts. OEM parts are manufactured by or for the vehicle's Original Equipment Manufacturer (OEM) according to OEM's specifications for U.S. distribution. OEM parts are available at OE/Vehicle dealerships or the specified supplier. OPT OEM (Optional OEM) or ALT OEM (Alternative OEM) parts are OEM parts that may be provided by or through alternate sources other than the OEM vehicle dealerships with discounted pricing. Asterisk (\*) or Double Asterisk (\*\*) indicates that the parts and/or labor data provided by third party sources of data may have been modified or may have come from an alternate data source. Tilde sign (~) items indicate MOTOR Not-Included Labor operations. The symbol (<>) indicates the refinish operation WILL NOT be performed as a separate procedure from the other panels in the estimate. Non-Original Equipment Manufacturer aftermarket parts are described as Non OEM, A/M or NAGS. Used parts are described as LKQ, RCY, or USED. Reconditioned parts are described as Recond. Recored parts are described as Recore. NAGS Part Numbers and Benchmark Prices are provided by National Auto Glass Specifications. Labor operation times listed on the line with the NAGS information are MOTOR suggested labor operation times. NAGS labor operation times are not included. Pound sign (#) items indicate manual entries.

Some 2023 vehicles contain minor changes from the previous year. For those vehicles, prior to receiving updated data from the vehicle manufacturer, labor and parts data from the previous year may be used. The CCC ONE estimator has a list of applicable vehicles. Parts numbers and prices should be confirmed with the local dealership.

The following is a list of additional abbreviations or symbols that may be used to describe work to be done or parts to be repaired or replaced:

### SYMBOLS FOLLOWING PART PRICE:

m=MOTOR Mechanical component. s=MOTOR Structural component. T=Miscellaneous Taxed charge category. X=Miscellaneous Non-Taxed charge category.

### SYMBOLS FOLLOWING LABOR:

D=Diagnostic labor category. E=Electrical labor category. F=Frame labor category. G=Glass labor category. M=Mechanical labor category. S=Structural labor category. (numbers) 1 through 4=User Defined Labor Categories.

### OTHER SYMBOLS AND ABBREVIATIONS:

Adj.=Adjacent. Algn.=Align. ALU=Aluminum. A/M=Aftermarket part. Bld=Blend. BOR=Boron steel. CAPA=Certified Automotive Parts Association. D&R=Disconnect and Reconnect. HSS=High Strength Steel. HYD=Hydroformed Steel. Incl.=Included. LKQ=Like Kind and Quality. LT=Left. MAG=Magnesium. Non-Adj.=Non Adjacent. NSF=NSF International Certified Part. O/H=Overhaul. Qty=Quantity. Refn=Refinish. Repl=Replace. R&I=Remove and Install. R&R=Remove and Replace. Rpr=Repair. RT=Right. SAS=Sandwiched Steel. Sect=Section. Subl=Sublet. UHS=Ultra High Strength Steel. N=Note(s) associated with the estimate line.

CCC ONE Estimating - A product of CCC Intelligent Services Inc.

The following is a list of abbreviations that may be used in CCC ONE Estimating that are not part of the MOTOR CRASH ESTIMATING GUIDE:

BAR=Bureau of Automotive Repair. EPA=Environmental Protection Agency. NHTSA= National Highway Transportation and Safety Administration. PDR=Paintless Dent Repair. VIN=Vehicle Identification Number.

**Preliminary Supplement 1 with Summary**

---

**Customer: sharp, clay co chief deputy**

**Job Number:**

2015 FORD Police Interceptor AWD (Fleet) 4D SED 6-3.7L Gasoline Sequential MPI

**PARTS SUPPLIER LIST**

<b>Line</b>	<b>Supplier</b>	<b>Description</b>	<b>Price</b>
14	National Autobody Parts Warehouse 2000 E Main Street Grand Prairie TX 75050 (800) 214-7222	#FO4050155 A/M Trans cooler Quote: 1709599099 Expires: 12/15/23	\$ 113.00





Document Name: Photo 01.jpg

Remarks:

CLAY COUNTY DEPUTY

**Karl Klement Ford**

2018 FORD SUPER DUTY PICKUP  
 2018 FORD SUPER DUTY PICKUP  
 2018 FORD SUPER DUTY PICKUP

38723  
 2018 FORD SUPER DUTY PICKUP  
 2018 FORD SUPER DUTY PICKUP

CLAY COUNTY DEPUTY

QTY	DESCRIPTION	UNIT PRICE	TOTAL PRICE
1	2018 FORD SUPER DUTY PICKUP	520.04	520.04
1	2018 FORD SUPER DUTY PICKUP	49.17	49.17
1	2018 FORD SUPER DUTY PICKUP	23.21	23.21
1	2018 FORD SUPER DUTY PICKUP	57.84	57.84
1	2018 FORD SUPER DUTY PICKUP	525.46	525.46
1	2018 FORD SUPER DUTY PICKUP	82.00	82.00
1	2018 FORD SUPER DUTY PICKUP	1098.37	1098.37
1	2018 FORD SUPER DUTY PICKUP	95.87	95.87
1	2018 FORD SUPER DUTY PICKUP	0.00	0.00
1	2018 FORD SUPER DUTY PICKUP	1178.00	1178.00

1546 1/3 PAGE 1/3

CLAY COUNTY DEPUTY

Document Name: Photo 01 (2).jpg

Remarks:



Document Name: Photo 02.jpg

Remarks:



Document Name: Photo 03.jpg

Remarks:





Document Name: Photo 04.jpg

Remarks:



Document Name: Photo 05.jpg

Remarks:



Document Name: Photo 06.jpg

Remarks:



Document Name: Photo 07.jpg

Remarks:



Document Name: Photo 08.jpg

Remarks:



Document Name: Photo 09.jpg

Remarks:





Document Name: Photo 10.jpg

Remarks:



Document Name: Photo 11.jpg

Remarks:



Document Name: Photo 12.jpg

Remarks:



Document Name: Photo 13.jpg

Remarks:





Document Name: Photo 14.jpg

Remarks:



Document Name: Photo 15.jpg

Remarks: